

# General Environmental Incident Summary

**Incident:** 3236      **Date/Time Notice:** 3/10/2014      10:50      **DEM Incident No:**  
**Responsible Party:** Border Plains Equipment  
**Date Incident:** 3/9/2014      **Time Incident:** 13:00      **Duration:** 2 hours  
**County:** Williams      **Twp:** 154      **Rng:** 101      **Sec:** 29      **Qtr:**  
**Lat:** 48.13929      **Long:** -103.69530      **Method:** Address matching  
**Location Description:** Border Plains Equipment  
13922 W. Front St  
Williston, ND 58801  
**Submitted By:** Mikhail Astvatsaturov      **Affiliation:** Assistant Manager  
**Address:** 13922 W. Front St  
**City:** Williston      **State:** ND      **Zip:** 58801

## Received By:

**Contact Person:** David Anfinson  
13922 W. Front ST  
Williston, ND 58801

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** Tank Overflow

**Description of Released Contaminant:** Used Motor Oil(Includes engine oil mostly, some residual antifreeze, some hydraulic oil)

**Volume Spilled:** 100.00 gallons      **Ag Related:** Yes

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

Technician was filling up a secondary container from the used oil tank. He forgot to shut off lever. Tank overflowed.

## Risk Evaluation:

No known risks to atmosphere or health hazard.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 04 - water and soil

## Potential Environmental Impacts:

Soil impact as well as some water impact. Contained to the parking/Lot of our dealership.

## Action Taken or Planned:

Majority of the oil was contained into large 250 gallon containers(2 full containers of water and oil mixture.We contained the spill to a retention area. Contacted a disposal company and will drop of contaminated oil & water. We are working on disposing retention area at this time.

**Wastes Disposal Location:** Prairie Disposal  
Tioga, N.D.  
O: 701.664.3383

**Agencies Involved:**

**Updates**

---

**Date:** 3/10/2014      **Status:** Reviewed; Followup Required      **Staff:** Roberts, Kris

**Updated Volume:**

**Notes:**

Release of used motor fluids to stormwater retention area. Followup is necessary.

---

**Date:** 4/2/2014      **Status:** Inspected      **Staff:** Martin, Russell

**Updated Volume:**

**Notes:**

4/2/2014 at 10:00, on location. Facility formerly known as Frontier Equipment, Inc. According to report contact, Garner Environmental Services was the cleanup company. Spill travelled south from tank, following grade of facility lot, turning east and ending at retention pond. No stain visible on frozen ground or in/around retention pond. Some stains visible on concrete pad around storage tank. They have applied absorbent material to remove free-standing fluid on the pad. The two 250-gallon containers will not be used again, except for other oil-based liquids.